

23(T)/2026 VIET NAM - NORTH EAST COAST - HAI PHONG - Buoyage.

Source: Hai Phong Port authority, Notice No. 629/2026/TBHH-CVHHHP

1. The lateral buoy, *HP55, Fl.G.3s*, has been temporarily removed from the position 20°50.00'N, 106°47.30'E to 20°50.02'N, 106°47.32'E.
2. The lateral buoy, *HP55A, Fl.G.3s*, has been temporarily removed from the position 20°49.94'N, 106°47.45'E to 20°49.96'N, 106°47.46'E.

(All positions are referred to WGS84 Datum)

Chart affected - VN50008

23(T)/2026 VIỆT NAM - BỜ BIỂN ĐÔNG BẮC BỘ - HẢI PHÒNG - Hệ thống phao.

Nguồn: Cảng vụ hàng hải Hải Phòng, Thông báo số 629/2026/TBHH-CVHHHP

1. Phao luồng, *HP55, Fl.G.3s*, được di chuyển tạm thời từ vị trí 20°50.00'N, 106°47.30'E đến 20°50.02'N, 106°47.32'E.
2. Phao luồng, *HP55A, Fl.G.3s*, được di chuyển tạm thời từ vị trí 20°49.94'N, 106°47.45'E đến 20°49.96'N, 106°47.46'E.

(Tất cả các vị trí được tham chiếu theo hệ tọa độ WGS84)

Hải đồ ảnh hưởng - VN50008